

# CONFIRMATION

Notification: 0000025926\_04\_06  
on changes according to EN 15267 regarding Certificate no. 0000025926\_04 dated 2 February 2015

---

<b>AMS designation:</b>	<b>MCS100FT for O<sub>2</sub>, CO, SO<sub>2</sub>, NO, NO<sub>2</sub>, HCl, HF, CH<sub>4</sub>, CO<sub>2</sub>, H<sub>2</sub>O, N<sub>2</sub>O, NH<sub>3</sub> and TOC</b>
<b>Manufacturer:</b>	<b>SICK AG Nimburger Straße 11 79276 Reute Germany</b>

---

**German Federal Environment Agency (UBA)**

**Announcement regarding the uniform practice in  
monitoring emissions and ambient air  
dated 3 July 2018  
Publication: BAnz AT 17.07.2018 B9**

**III. Notifications as regards the uniform practice for the continuous monitoring of emissions and ambient air:**

**25 Notification as regards Federal Environment Agency (UBA) notices dated 10 January 2011 (BAnz. p. 294, chapter I number 3.1) and dated 13 July 2017 (BAnz AT 31.07.2017 B12, chapter II 22<sup>nd</sup> notification)**

The MCS100FT measuring system for O<sub>2</sub>, CO, SO<sub>2</sub>, NO, NO<sub>2</sub>, HCl, HF, CH<sub>4</sub>, CO<sub>2</sub>, H<sub>2</sub>O, N<sub>2</sub>O, NH<sub>3</sub> and TOC manufactured by SICK AG now provides a digital Modbus interface (TCP/IP) in accordance with VDI 4201 parts 1 and 3.


Report no. 936/21242227/A dated 2 May 2018 issued by TÜV Rheinland Energy GmbH presents the corresponding test results. The current software versions are:


MCS100FT: 9191787\_YNO9,  
SCU-P100: 9158931\_YXS3,  
FID: 9185196\_YNO9\_151125\_0800

Statement issued by TÜV Rheinland Energy GmbH dated 2 May 2018

---

TÜV Rheinland Energy GmbH  
Cologne, 1 August 2018

  
i. V. Dipl.-Ing. Guido Baum

  
i. A. Dipl.-Ing. Carsten Röllig

[www.umwelt-tuv.eu](http://www.umwelt-tuv.eu)  
tre@umwelt-tuv.eu  
Phone: +49 221 806-5200

TÜV Rheinland Energy GmbH  
Am Grauen Stein  
51105 Köln

Test institute accredited to EN ISO/IEC 17025:2005 by DAkkS (German Accreditation Body).  
This accreditation is limited to the accreditation scope defined in the enclosure to the certificate D-PL-11120-02-00.